

TH



A NEW SYSTEM

OF

HAND-RAILING.

CUT SQUARE TO THE PLANK, WITHOUT THE AID OF FALLING MOULDS.

A NEW AND EASY METHOD OF FORMING HAND-RAILS.

Containing a Large Number of Illustrations of Hand-Rails, with Full Instructions for Working Them.

BY

AN OLD STAIR-BUILDER.

REVISED AND CORRECTED EDITION


NEW YORK:
THE INDUSTRIAL PUBLICATION COMPANY.
1885



PREFACE.

The following method of getting out wreaths for hand-railing, while not new, is not generally known in this country, which is to be regretted. By this method much time and material are saved, and the wreaths formed with more accuracy than cutting them out by the older methods, as any wreath whatever may be cut out square from a plank of the same thickness as the diameter of a circle described round a section of the rail.

In the annexed cut, A B shows the thickness of the plank. But it is better for the learner to allow the plank 4 inch thicker, as it leaves more for



squaring the rail. By this method the same bevel applies to both ends of the wreath on the square joint, for stairs with any number of winders in the well; this ensures the rail rising equally all round the well, and not quick in one part and flat in another.

All wreaths are cut out square from the plank with square joints, and so accurate are the bevels and joints that the rail may be cleaned up ready for polishing before it leaves the beach.

Seven complete examples are given, with ample illustrations and descriptive text; these examples being quite sufficient to enable the student to build a rail over any kind of a stair, no matter how many winders there may be,or how they are arranged.

New York, 1885.

INTRODUCTION.

Before proceeding to describe the method of obtaining the lines necessary for the correct formation of Hand-rails, it is deemed advisable to present for the student's use a rudimentary treatise on what is known as Carpenter's Geometry, as it is felt that a knowledge of this will materially aid the young beginner to a better understanding of the principles involved in the work.

The following treatise, which is taken from "Practical Carpentry," is simple and easily understood. Let me add, however, that, although a knowledge of geometry will greatly help the student to understand the method herein described, such knowledge is not absolutely necessary, as the Art of Hand-railing, as here presented, may be efficiently acquired without it.

TABLE OF CONTENTS.

PART I.

PAGE

Geometry, Straight Lines. - Curved Lines. - Solids. - Compound Lines. -Parallel Lines,-Oblique or Converging Lines,-Plane Figures,-Angles, -Right Angles, -Acute Angles, -Obtuse Angles, -Right-angled Triangles, - Quadrilateral Figures, - Parallelograms, - Rectangles, -Squares. - Rhomboids. - Trapeziums. - Trapezoids. - Diagonals. - Polycons — Pentagons — Hexagons — Heptagons — Octagons — Circles — Chords, -Tangents, -Sectors, -Ouadrants, -Arcs, -Concentric and Eccentric Circles.—Altitudes.—Problems I, to XXIX.—Drawing of Angles. -Construction of Geometrical Figures,—Bisection of Lines,—Trisection of Lines and Angles,-Division of Lines into any Number of Parts,-Construction of Triangles, Squares and Parallelograms,—Construction of Proportionate Squares.—Construction of Polygons,—Areas of Polygons. -Areas of Concentric Rings and Circles, -Segments of Circles,-The use of Ordinates for Obtaining Arcs of Circles .- Drawing an Ellipse with a Trammel,-Drawing an Ellipse by means of a String.-Same by Ordinates,-Raking Ellipses,-Ovals,-Sixty-two Illustrations,-Tangents and Diagrams for Handrailing.—Three Illustrations,

PART II.

Lines and Method for Making the Wreaths for Stairs with Four Winders in the Well. Four Illustrations and Diagrams,-Lines and Method for Making the Wreaths for Stairs with Six Winders in the Well. Three Illustrations and Working Diagrams.-Lines and Method for Making the Wreaths for Stairs with Three Winders in Half the Well, and Landing in the Centre of the Well, Four Illustrations and Working Diagrams .-Method of Making the Wreaths for Stairs with One Riser in the Centre of Well. With Three Illustrations and Working Diagrams.-How to Make the Wreaths for Level Landing Stairs, the distance between Centre of Rails across the Well being equal to the Tread of a Step, or nearly so. With Three Illustrations and Working Diagrams, -- How to Make the Wreath for Quarter-landing Stairs, having One Winder in the Well. Three Illustrations and Working Diagrams, -How to Make a Wreath for Quarter-landing Stairs, with Risers on the Line of Spring. Three Illustrations and Working Dlagrams. -- 35-65



HAND-RAILING.

PART L-GEOMETRY.

EFORE a knowledge of geometry can be acquired, it will be necessary to become acquainted with some of the terms and definitions used in the science of geometry,

and to this end the following terms and explanations are given, though it must be understood that these are only a few of the terms used in the science, but they are sufficient for our purposes:


- 1. A*Point has position but not magnitude. Practically, it is represented by the smallest visible mark or dot, but geometrically understood, it occupies no space. The extremities or ends of lines are points; and when two or more lines cross one another, the places that mark their intersections are also points.
- 2. A *Line* has length, without breadth or thickness, and, consequently. a true geometrical line cannot be exhibited; for however finely a line may be drawn, it will always occupy a certain extent of space.
- 3. A Superficies or Surface has length and breadth, but no thickness. For instance, a shadow gives a very good representation of a superficies: its length and breadth can be measured; but it has no depth or substance. The quantity of space contained in any plane surface is called its area.
- 4. A Plane Superficies is a flat surface, which will coincide with a straight line in every direction.

- 5. A Curved Superficies is an uneven surface, or such as will not coincide with a straight line in all directions. By the term surface is generally understood the outside of any body or object; as, for instance, the exterior of a brick or stone, the boundaries of which are represented by lines, either straight or curved, according to the form of the object. We must always bear in mind, however, that the lines thus bounding the figure occupy no part of the surface; hence the lines or points traced or marked on any body or surface, are merely symbols of the true geometrical lines or points.
- 6. A Solid is anything which has length, breadth and thickness; consequently, the term may be applied to any visible object containing substance; but, practically, it is understood to signify the solid contents or measurement contained within the different surfaces of which any body is formed.
- 7. Lines may be drawn in any direction, and are termed straight, curved, mixed, concave, or convex lines, according as they correspond to the following definitions.
- 8. A Straight Line is one every part of which A Blies in the same direction between its extremities, and is, of course, the shortest distance between two points, as from A to B, Fig. 1.
- 9. A *Curved Line* is such that it does not lie in a straight direction between its extremities, but is continually changing by inflection. It may be either regular or irregular.
- 10. A Mixed or Compound Line is composed of straight and curved lines, connected in any form.
- 11. A Concave or Convex Line is such that it cannot be cut by a straight line in more than two points; the concave or hollow side is turned towards the straight line, while the convex or swelling side looks away from it. For instance, the inside of a basin is concave—the outside of a ball is convex.
- 12. Parallel Straight Lines have no inclination, but are everywhere at an equal distance from each other; consequently they can never meet, though produced or continued to infinity in either or both directions. Parallel lines may be either straight or curved,

provided they are equally distant from each other throughout their extension.

- 13. Oblique or Converging Lines are straight lines, which, if continued, being in the same plane, change their distance so as to meet or intersect each other.
- 14. A Plane Figure, Scheme, or Diagram, is the lineal representation of any object on a plane surface. If it is bounded by straight lines, it is called a rectilineal figure; and if by curved lines, a curvilineal figure.
- 15. An Angle is formed by the inclination of two lines meeting in a point: the lines thus forming the angle are called the sides; and the point where the lines meet is called the vertex or angular point.

When an angle is expressed by three letters, as A B C, Fig. 2, the middle letter B should always denote the angular point: where



there is only one angle, it may be expressed more concisely by a letter placed at the angular point only, as the angle at A, Fig. 3.

16. The quantity of an angle is estimated by the arc of any circle contained between the two sides or lines forming the angle; the junction of the two lines, or vertex of the angle, being the centre from which the arc is described. As the circumferences of all circles are proportional to their diameters, the arcs of similar sectors also bear the same proportion to their respective circumferences; and, consequently, are proportional to their diameters, and, of course, also to their radii or semi-diameters. Hence, the

proportion which the arc of any circle bears to the circumference of that circle, determines the magnitude of the angle. From this it is evident that the quantity or magnitude of angles does not depend upon the length of the sides or radii forming them, but wholly upon the number of degrees contained in the arc cut from the circumference of the circle by the opening of these lines. The circumference of every circle is divided by mathematicians into 360 equal parts, called degrees; each degree being again subdivided into 60 equal parts, called minutes, and each minute into 60 parts, called seconds. Hence, it follows that the arc of a quarter circle or quadrant includes 90 degrees; that is, one-fourth part of 360 degrees. By dividing a quarter circle, that is, the portion of the circumference of any circle contained between two radii forming a right angle, into 90 equal parts, or, as is shown in Fig. 4, into nine equal parts of 10 degrees each, then drawing straight lines from the centre through each point of division in the arc; the right angle will be divided into nine equal angles, each containing 10 degrees. Thus, suppose B C the horizontal line, and A B the perpendicular ascending from it, any line drawn from B-the centre from which the arc is described—to any point in its circumference, determines the degree of inclination or angle formed between it and the horizontal line B C. Thus, a line from the centre B to the tenth degree, separates an angle of 10 degrees, and so on. manner the various slopes or inclinations of angles are defined,

17. A Right Angle is produced by one straight line standing upon another, so as to make the adjacent angles equal. This is what workmen call "square," and is the most useful figure they employ.

18. An Acute Angle is less than a right angle, or less than 90 degrees.

19. An *Obtuse Angle* is greater than a right angle or square, or more than 90 degrees.

The number of degrees by which an angle is less than 90 degrees is called the complement of the angle. Also, the difference between an obtuse angle and a semicircle, or 180 degrees, is called the supplement of that angle.


- 20. Plane Figures are bounded by straight lines, and are named according to the number of sides which they contain. Thus, the space included within three straight lines, forming three angles, is called a trilateral figure or triangle.
- 21. A Right-Angled Triangle has one right angle: the sides forming the right angle are called the base and perpendicular; and the side opposite the right angle is named the hypothenuse. An equilateral triangle has all its sides of equal length. An isosceles triangle has only two sides equal; a scalene triangle has all its sides unequal. An acute-angled triangle has all its angles acute, and an obtused-angled triangle has one of its angles only obtuse.

The triangle is one of the most useful geometrical figures for the mechanic in taking dimensions; for since all figures that are bounded by straight lines are capable of being divided into triangles, and as the form of a triangle cannot be altered without changing the length of some one of its sides, it follows that the true form of any figure can be preserved if the length of the sides of the different triangles into which it is divided is known; and the area of any triangle can easily be ascertained by the same rule, as will be shown further on.


Quadrilateral Figures are literally four-sided figures. They are also called quadrangles, because they have four angles.

- 22. A Parallelogram is a figure whose opposite sides are parallel, as A B C D, Fig. 5.
- 23. A Rectangle is a parallelogram having four right angles, as Λ B C D, in Fig. 5.
- 24. A Square is an equilateral rectangle, having all its sides equal, like Fig. 5.
- 25. An *Oblong* is a rectangle whose adjacent sides are unequal, as the parallelogram shown at Fig. 10.
- 26. A *Rhombus* is an oblique-angled figure, or parallelogram having four equal sides, whose opposite angles only are equal, as c, Fig. 6.
- 27. A Rhomboid is an oblique angled parallelogram, of which the adjoining sides are unequal, as D, Fig. 7.

- .28. A *Trapezium* is an irregular quadrilateral figure, having no two sides parallel, as E, Fig. 8.
- 29. A *Trapezoid* is a quadrilateral figure, which has two of its opposite sides parallel, and the remaining two neither parallel nor equal to one another, as F, Fig. 9.



- 30. A *Diagonal* is a straight line drawn between two opposite angular points of a quadrilateral figure, or between any two angular points of a polygon. Should the figure be a parallelogram, the diagonal will divide it into two equal triangles, the opposite sides and angles of which will be equal to one another. Let A B C D, Fig. 10, be a parallelogram; join A C, then A C is a diagonal, and the triangles A D C, A B C, into which it divides the parallelogram, are equal.
- 31. A plane figure, bounded by more than four straight lines, is called a *Polygon*. A regular polygon has all its sides equal, and consequently its angles are also equal, as K, L, M, and N, Figs.



- 12-15. An irregular polygon has its sides and angles unequal, as H, Fig. 11. Polygons are named according to the number of their sides or angles, as follows:—
 - 32. A Pentagon is a polygon of five sides, as н or к, Figs. 11, 12.
 - 33. A Hexagon is a polygon of six sides, as L, Fig. 13.
 - 34. A Heptagon has seven sides, as M, Fig. 14.


35. An Octagon has eight sides, as N, Fig. 15.

An Enneagon has nine, a Decagon ten, an Undecagon eleven, and a Dodecagon twelve sides. Figures having more than twelve sides are generally designated Polygons, or many-angled figures.

36. A Circle is a plane figure bounded by one uniformly curve I line, $b \in d$ (Fig. 16), called the circumference, every part of which is equally distant from a point within it, called the centre, as a.

37. The *Radius* of a circle is a straight line drawn from the centre to the circumference; hence, all the radii (plural for radius) of the same circle are equal, as b a, c a, c a, c a, in Fig. 16.

38. The *Diameter* of a circle is a straight line drawn through the centre, and terminated on each side by the circumference; conse-



quently the diameter is exactly twice the length of the radius; and hence the radius is sometimes called the semi-diameter. (See b a c, Fig. 16.)

49. The *Chord* or *Subtens* of an arc is any straight line drawn from one point in the circumference of a circle to another, joining the extremities of the arc, and dividing the circle either into two equal, or two unequal parts. If into equal parts, the chord is also the diameter, and the space included between the arc and the diameter, on either side of it, is called a semicircle, as b a e in Fig. 16. If the parts cut off by the chord are unequal, each of them is called a *segment* of the circle. The same chord is therefore common to two arcs and two segments; but, unless when stated otherwise, it is always understood that the lesser arc or segment is spoken of, as in Fig. 16, the chord e d is the chord of the arc e e d.

If a straight line be drawn from the centre of a circle to meet the chord of an arc perpendicularly, as af, in Fig. 16, it will divide the chord into two equal parts, and if the straight line be produced

to meet the arc, it will also divide it into two equal parts, as cf, fd.

Each half of the chord is called the sine of the half-arc to which it is opposite; and the line drawn from the centre to meet the chord perpendicularly, is called the co-sine of the half-arc. Consequently, the radius, the sine, and co-sine of an arc form a right angle.

40. Any line which cuts the circumference in two points, or a chord lengthened out so as to extend beyond the boundaries of the circle, such as g h in Fig. 17, is sometimes called a *Secant*. But, in trigonometry, the secant is a line drawn from the centre through one extremity of the arc, so as to meet the tangent which is drawn from the other extremity at right angles to the radius. Thus, $\mathbf{F} \in h$ is the secant of the arc $e \in h$, or the angle $e \in h$ e, in Fig. 17.

41. A Tangent is any straight line which touches the circumference of a circle in one point, which is called the point of contact, as in the tangent line e b, Fig. 17.

42. A Sector is the space included between any two radii, and that portion of the circumference comprised between them: e e F is a sector of the circle a f e e, Fig. 17.

43. A Quadrant, or quarter of a circle, is a sector bounded by two radii, forming a right angle at the centre, and having one-fourth part of the circumference for its arc, as Ffd, Fig. 7.

44. An Arc, or Arch, is any portion of the circumference of a circle, as c d e, Fig. 17.

It may not be improper to remark here that the terms circle and circumference are frequently misapplied. Thus we say, describe a circle from a given point, etc., instead of saying describe the circumference of a circle—the circumference being the curved line thus described, everywhere equally distant from a point within it, called the centre; whereas the circle is properly the superficial space included within that circumference.


45. Concentric Circles are circles within circles, described from the same centre; consequently, their circumferences are parallel to one another, as Fig. 18.

46. Eccentric Circles are those which are not described from the

same centre; any point which is not the centre is also eccentric in reference to the circumference of that circle. Eccentric circles may also be tangent circles; that is, such as come in contact in one point only, as Fig. 19.

47. Altitude. The height of a triangle or other figure is called its altitude. To measure the altitude, let fall a straight line from the vertex, or highest point in the figure, perpendicular to the base or opposite side; or to the base continued, as at B D, Fig. 20, should the form of the figure require its extension. Thus C D is the altitude of the triangle A B C.

We have now described all the figures we shall require for the purpose of thoroughly understanding all that will follow in this book; but we would like to say right here that the student who has time should not stop at this point in the study of geometry, for the time spent in obtaining a thorough knowledge of this useful



science will bring in better returns in enjoyment and money, than if expended for any other purpose.

We will now proceed to explain how the figures we have described can be constructed. There are several ways of constructing nearly every figure we produce, but we have chosen those methods that seemed to us the best, and to save space have given as few examples as possible consistent with efficiency.


PROBLEM I.—Through a given point c (Fig. 18 a), to draw a straight line parallel to a given straight line A B.

In A B (Fig. 18 a) take any point d, and from d as a centre with the radius d C, describe an arc C e, cutting A B in e, and from C as a

centre, with the same radius, describe the arc dD, make dD equal to CC, join CD, and it will be parallel to AB.

PROBLEM II.—To make an angle equal to a given rectilineal angle.

From a given point E (Fig. 19 a), upon the straight line E F, to make an angle equal to the given angle A B C. From the angular point B, with any radius, describe the arc e f, cutting B C and B A in the points e and f. From the point E on E F with the same radius,



describe the arc hg, and make it equal to the arc ef; then from E, through g, draw the line ED: the angle DEF will be equal to the angle ABC.

PROBLEM III.—To bisect a given angle.

Let A B C (Fig. 20 a) be the given angle. From the angular point B, with any radius, describe an arc cutting B A and B C in the points d and e; also, from the points d and e as centres, with any radius greater than half the distance between them, describe arcs cutting each other in f; through the points of intersection f, draw B f D: the angle A B C is bisected by the straight line B D; that is, it is divided into two equal angles, A B D and C B D.

PROBLEM IV.—To trisect or divide a right angle into three equal angles.


Let A B C (Fig. 21) be the given right angle. From the angular

point B, with any radius, describe an arc cutting B A and B C in the points d and g; from the points d and g, with the radius B d or B g, describe the arcs cutting the arc d g in e and f; join B e and B f: these lines will trisect the angle A B C, or divide it into three equal angles.

The trisection of an angle can be effected by means of elementary geometry only in a very few cases; such, for instance, as those where the arc which measures the proposed angle is a whole circle, or a half, a fourth, or a fifth part of the circumference. Any angle of a pentagon is trisected by diagonals, drawn to its opposite angles.

PROBLEM V.—From a given point c, in a given straight line A B, to erect a perpendicular.

From the point c (Fig. 22), with any radius less than C A or C B, describe arcs cutting the given line A B in d and e; from these




points as centres, with a radius greater than c d or c e, describe arcs intersecting each other in f: join c f, and this line will be the perpendicular required.

Another Method.—To draw a right angle or erect a perpendicular by means of any scale of equal parts, or standard measure of inches, feet, yards, etc., by setting off distances in proportion to the numbers 3, 4 and 5, or 6, 8 and 10, or any numbers whose squares correspond to the sides and hypothenuse of a right-angled triangle.

From any scale of equal parts, as that represented by the line D (Fig. 23), which contains 5, set off from B, on the line A B, the distance B e, equal to 3 of these parts; then from B, with a radius equal to 4 of the same parts, describe the arc a b: also from e as a

centre, with a radius equal to 5 parts, describe another arc intersecting the former in C; lastly join BC; the line BC will be perpendicular to AB.

This mode of drawing right angles is more troublesome upon paper than the method previously given; but in laying out grounds or foundations of buildings it is often very useful, since only with a ten-foot pole, tape line, or chain, perpendiculars may be set out very accurately. The method is demonstrated thus:—The square of the hypothenuse, or longest side of a right-angled triangle, being equal to the sum of the squares of the other two sides, the same property must always be inherent in any three numbers, of which




the squares of the two lesser numbers, added together, are equal to the square of the greater. For example, take the numbers 3, 4, and 5; the square of 3 is 9, and the square of 4 is 16; 16 and 9, added together make 25, which is 5 times 5, or the square of the greater number. Although these numbers, or any multiple of them, such as 6, 8, 10, or 12, 16, 20, etc., are the most simple, and most easily retained in the memory, yet there are other numbers, very different in proportion, which can be made to serve the same purpose. Let n denote any number; then $n^2 + 1$, $n^2 - 1$, and 2n, will represent the hypothenuse, base, and perpendicular of a right-angled triangle. Suppose n = 6, then $n^2 + 1 = 37$, $n^2 - 1 = 35$, and 2n = 12: hence, 37, 35, and 12 are the sides of a right-angled triangle. A knowledge of this problem will often prove of the greatest service to the workman.

PROBLEM VI .- To bisect a given straight line.

Let A B (Fig. 24) be the given straight line. From the extreme points A and B as centres, with any equal radii greater than half the length of A B, describe arcs cutting each other in C and D: a straight line drawn through the points of intersection C and D, will bisect the line A B in ϵ .

PROBLEM VII.—To divide a given line into any number of equal parts.

Let A B (Fig. 25) be the given line to be divided into five equal parts. From the point A draw the straight line A C, forming any angle with A B. On the line A C, with any convenient opening of the compasses, set off five equal parts towards C; join the extreme



points C B; through the remaining points 1, 2, 3, and 4, draw lines parallel to B C, cutting A B in the corresponding points, 1, 2, 3, and 4: AB will be divided into five equal parts, as required.


the figure, similar divisions can be obtained in lines of any given length.

PROBLEM VIII.—To describe an equilateral triangle upon a given straight line.

Let A B (Fig. 27) be the given straight line. From the points A and B, with a radius equal to A B, describe arcs intersecting each other in the point c. Join c A and c B, and A B C will be the equilateral triangle required.

PROBLEM IX.—To construct a triangle whose sides shall be equal to three given lines, F, E, D.

Draw AB (Fig. 28) equal to the given line F. From A as a centre, with a radius equal to the line E, describe an are; then



from B as a centre, with a radius equal to the line D, describe another arc intersecting the former in C; join C A and C B, and A B C will be the triangle required.

PROBLEM X.—To describe a rectangle or parallelogram having one of its sides equal to a given line, and its area equal to that of a given rectangle.


Let AB (Fig. 29) be the given line, and CDEF the given rectangle. Produce CE to G, making EG equal to AB; from G draw GK parallel to EF, and meeting DF produced in II. Draw the diagonal GF, extending it to meet CD produced in L; also draw LK parallel to DH, and produce EF till it meet LK in M; then FMKH is the rectangle required.

Equal and similar rhomboids or parallelograms of any dimensions may be drawn after the same manner, seeing the complements of the parallelograms which are described on or about the diagonal of any parallelogram, are always equal to each other; while the parallelograms themselves are always similar to each other, and to the original parallelogram about the diagonal of which they are constructed. Thus, in the parallelogram C G K L the complements C E F D and F M K H are always equal, while the parallelograms E F H G and D F M L about the diagonal G L, are always similar to each other, and to the whole parallelogram C G K L.

PROBLEM XI.—To describe a square equal to two given squares.


Let A and B (Fig. 30) be the given squares. Place them so that a side of each may form the right angle D C E; join D E, and upon this hypothenuse describe the square D E G F, and it will be equal

to the sum of the squares A and B, which are constructed upon the legs of the right-angled triangle D C E. In the same manner, any other rectilineal figure, or even circle, may be found equal to the sum of other two similar figures or circles. Suppose the lines C D and C E to be the diameters of two circles, then D E will be the diameter of a third, equal in area to the other two circles. Or suppose C D and C E to be the like sides of any two similar figures, then D E will be the corresponding side of another similar figure equal to both the former.



Problem XII.—To describe a square equal to any number of given squares.

Let it be required to construct a square equal to the three given squares A, B, and C (Fig. 31). Take the line D E, equal to the side of the square C. From the extremity D erect D F perpendicular to D E, and equal to the side of the square B; join E F; then a square described upon this line will be equal to the sum of the two given squares C and B. Again, upon the straight line E F erect the per-




pendicular F G, equal to the side of the third given square A; and join G E, which will be the side of the square G E H K, equal in area to A, B, and C. Proceed in the same way for any number of given squares.

PROBLEM XIII.—Upon a given straight line to describe a regular polygon.

To produce a regular pentagon draw A B to C (Fig. 32), so that B C may be equal to A B; from B as a centre, with the radius B A or B C describe the semicircle A D C; divide the semi-circumference A D C into as many equal parts as there are parts in the required polygon, which,

in the present case, will be five; through the second division from c draw the straight line B D, which will form another side of the figure. Bisect A B at e, and B D at f, and draw e G and f G per-

pendicular to A B and B D; then G, the point of intersection, is the centre of a circle, of which A B and D are points in the circumference. From G, with a radius equal to its distance from any of these points, describe the circumference A B D H K; then producing the dotted lines from the centre B, through the remaining divisions in the semicircle



A D C, so as to meet the circumference of which C is the centre, in H and K, these points will divide the circle A B D H K into the number of parts required, each part being equal to the given side of the pentagon.

From the preceding example it is evident that polygons of any number of sides may be constructed upon the same principles, because the circumferences of all circles, when divided into the same number of equal parts, produce equal angles; and, consequently, by dividing the semi-circumference of any given circle into the


number of parts required, two of these parts will form an angle which will be subtended by its corresponding part of the whole circumference. And as all regular polygons can be inscribed in a circle, it must necessarily follow, that if a circle be described through three given angles of that polygon, it will contain the number of sides or angles required.

The above is a general rule, by which all regular polygons may be described upon a given straight line; but there are other methods by which many of them may be more expeditiously constructed, as shown in the following examples:—

PROBLEM XIV.—Upon a given straight line to describe a regular pentagon.

Let A B (Fig. 33) be the given straight line; from its extremity B erect B c perpendicular to A B, and equal to its half. Join A c, and produce it till c d be equal to B c, or half the given line

to us half. Join A ℓ , and produce it till ℓ d be equal to B ℓ , or half the given line A B. From A and B as centres, with a radius equal to B d, describe arcs intersecting each other in ℓ , which will be the centre of the circumscribing circle A B F G H. The side A B applied successively to this circumference, will give the angular points of the pentagon; and these



being connected by straight lines will complete the figure.


PROBLEM XV.—Upon a given straight line to describe a regular hexagon.

Let A B (Fig. 34) be the given straight line. From the extremities A and B as centres, with the radius A B describe arcs cutting each other in g. Again from g, the point of intersection, with the same radius, describe the circle A B C, which will contain the given side A B six times when applied to its circumference, and will be the hexagon required.

PROBLEM XVI.—To describe a regular octagon upon a given straight line.

Let A B (Fig. 35) be the given line. From the extremities A and B erect the perpendiculars A E and B F; extend the given

line both ways to k and l, forming external right angles with the lines a E and B F. Bisect these external right angles, making each of the bisecting lines a H and B C equal to the given line A B. Draw H G and C D parallel to A E of B F, and each equal in length to A B. From G draw G E parallel to B C, and intersecting A E in E, and from D draw D F parallel to A H, intersecting B F in F. Join E F, and A B C D F E G H is the octagon required. Or from D



and G as centres, with the given line A B as radius, describe arcs cutting the perpendiculars A E and B F in E and F, and join G E, E F, F D, to complete the octagon.

Otherwise, thus.—Let A B (Fig. 36) be the given straight line on which the octagon is to be described. Bisect it in a, and draw the perpendicular a b equal to A a or B a. Join A b, and produce a b to c, making b c equal to A b; join also A c and B c, extending them so as to make c E and c F each equal to A c or B c. Through c draw C c G at right angles to A E. Again, through the same point c, draw D H at right angles to B F, making each of the lines c C, c D, c G, and c H equal to A c or c B, and consequently equal to one another. Lastly, join B C, C D, D E, E F, F G, G H, H A; A B C D E F G H will be a regular octagon described upon A B, as required.


PROBLEM XVII.—In a given square to inscribe a given octagon.

Let A B C D (Fig. 37) be the given square. Draw the diagonals A C and B D, intersecting each other in e; then from the angular points A B C and D as centres, with a radius equal to half the diagonal, viz., A e or C e, describe arcs cutting the sides of the

square in the points f, g, h, k, l, m, n, o, and the straight lines o f, g, h, k, l, and m, joining these points will complete the octagon, and be inscribed in the square A B C D, as required.

PROBLEM XVIII .- To find the area of any regular polygon.

Let the given figure be a hexagon; it is required to find its area. Bisect any two adjacent angles, as those at A and B (Fig. 38), by the straight lines A c and B C, intersecting in C, which will be the



centre of the polygon. Mark the altitude of this elementary triangle by a dotted line drawn from c perpendicular to the base A B; then multiply together the base and altitude thus found, and this product by the number of sides: half gives the area of the whole figure.


Or otherwise, thus.—Draw the straight line D E, equal to six times, i. e., as many times A B, the base of the elementary triangle, as there are sides in the given polygon. Upon D E describe an isosceles triangle, having the same altitude as A B C, the elementary triangle of the given polygon; the triangle thus constructed is equal in area to the given hexagon; consequently, by multiplying the base and altitude of this triangle together, half the product will be the area required. The rule may be expressed in other words, as follows:—The area of a regular polygon is equal to its perimeter, multiplied by half the radius of its inscribed circle, to which the sides of the polygon are tangents.

PROBLEM XIX.—To describe the circumference of a circle through three given points.

Let A, B, and C (Fig. 39) be the given points not in a straight line. Join A B and B C; bisect each of the straight lines A B and B C by perpendiculars meeting in D; then A, B and C are all equidistant from D; therefore a circle described from D, with the radius DA, DB, or DC, will pass through all the three points as required.

PROBLEM XX.—To divide a given circle into any number of equal or proportional parts by concentric divisions.

Let ABC (Fig. 40) be the given circle, to be divided into five equal parts. Draw the radius AD, and divide it into the same



number of parts as those required in the circle; and upon the radius thus divided, describe a semicircle: then from each point of division on A D, erect perpendiculars to meet the semi-circumference in e, f, g, and h. From D, the centre of the given circle, with radii extending to each of the different points of intersection on the semicircle, describe successive circles, and they will divide the given circle into five parts of equal area as required; the centre part being also a circle, while the other four will be in the form of rings.

PROBLEM XXI.—To divide a circle into three concentric parts, bearing to each other the proportion of one, two, three, from the centre.


Draw the radius A D (Fig. 41), and divide it into six equal parts. Upon the radius thus divided, describe a semicircle: from the first and third points of division, draw perpendiculars to meet the semicircumference in e and f. From D, the centre of the given circle, with radii extending to e and f, describe circles which will divide the given circle into three parts, bearing to each other the same proportion as the divisions on A D, which are as 1, 2 and 3. In like manner circles may be divided in any given ratio by concentric divisions.

PROBLEM XXII.—To draw a straight line equal to any given are of a circle.

Let A B (Fig. 42) be the given arc. Find c the centre of the arc, and complete the circle A D B. Draw the diameter B D, and produce it to E, until D E be equal to C D. Join A E, and extend it so as to meet a tangent drawn from B in the point F; then B F will be nearly equal to the arc A B.

The following method of finding the length of an arc is equally simple and practical, and not less accurate than the one just given.

Let A B (Fig. 43) be the given arc. Find the centre c, and join A B, B C, and C A. Bisect the arc A B in D, and join also C D; then through the point D draw the straight line E D F, at right



angles to CD, and meeting CA and CB produced in E and F. Again, bisect the lines A E and BF in the points G and H. A straight line GH, joining these points, will be a very near approach to the length of the arc AB.

Seeing that in very small arcs the ratio of the chord to the double tangent or, which is the same thing, that of a side of the inscribed to a side of the circumscribing polygon, approaches to a ratio of equality, an arc may be taken so small, that its length shall differ from either of these sides by less than any assignable quantity; therefore, the arithmetical mean between the two must differ from the length of the arc itself by a quantity less than any that can be assigned. Consequently the smaller the given arc, the more nearly will the line found by the last method approximate to the exact length of the arc. If the given arc is above 60 degrees, or two-thirds of a quadrant, it ought to be bisected, and the length of the

semi-arc thus found being double, will give the length of the whole arc.

These problems are very useful in obtaining the lengths of veneers or other materials required for bending round soffits of door and window-heads.

PROBLEM XXIII.—To describe the segment of a circle by means of two laths, the chord and versed sine being given.

Take two rods, EB, BF (Fig. 44), each of which must be at least equal in length to the chord of the proposed segment AC: join them together at B, and expand them, so that their edges shall pass through the extremities of the chord, and the angle where they join shall be on the extremity B of the versed sine DB, or height of the segment. Fix the rods in that position by the cross piece gh, then by guiding the edges against pins in the extremities of the chord line AC, the curve ABC will be described by the point B.

PROBLEM XXIV.—Having the chord and versed sine of the segment of a circle of large radius given, to find any number of points in the curve by means of intersecting lines.

Let AC be the chord and DB the versed sine.


Through B (Fig. 45) draw E F indefinitely and parallel to A C; join A B, and draw A E at right angles to A B. Draw also A G at



right angles to AC, or divide AD and EB into the same number of equal parts, and number the divisions from A and E respectively, and join the corresponding numbers by the lines 11,22,33. Divide also AG into the same number of equal parts as AD of EB, numbering the divisions from Aupwards, 1,2,3, etc.; and from the points , 2 and 3, draw lines to B; and the points of intersection of these, with the other lines at h, k, l, will be points in the curve required. Same with BC.

Another Method.—Let AC (Fig. 46) be the chord and DB the versed sine. Join AB, BC, and through Bdraw EF parallel to AC.

From the centre B, with the radius B A or B C, describe the arcs A E, C F. and divide them into any number of equal parts, as 1, 2, 3: from the divisions 1, 2, 3, draw radii to the centre B, and divide each radius into the same number of equal parts as the arcs A E



and CF; and the points g, h, l, m, n, o, thus obtained, are points in the required curve.

These methods, though not absolutely correct, are sufficiently accurate when the segment is less than the quadrant of a circle.

PROBLEM XXV.—To draw an ellipse with the trammel.

The trammel is an instrument consisting of two principal parts, the fixed part in the form of a cross E F G H (Fig. 47), and the moveable piece or tracer k/m. The fixed piece is made of two rectangular bars or pieces of wood, of equal thickness, joined together so as to be in the same plane. On one side of the frame so formed, a groove is made, forming a right-angled cross. In the

groove two studs, k and l, are fitted to slide freely, and carry attached to them the tracer k l m. The tracer is generally made to slide through a socket fixed to each stud, and provided with a screw or wedge, by which the distance apart of the studs may be regulated. The tracer has another slider m, also adjustable,





Fig. 47.

which carries a pencil or point. The instrument is used as follows:—Let $A \in B$ the major, and $B \in B$ the minor axis of an ellipse: lay the cross of the trammel on these lines, so that the centre lines of it may coincide with them; then adjust the sliders of the tracer, so that the distance between $A \in A$ and $B \in B$ and $B \in B$ the minor axis, and the distance between $A \in A$ and $B \in B$ and $B \in B$ the minor axis, and the distance between $A \in A$ and $B \in B$ the minor axis, and the distance between $A \in A$ and $B \in B$ the minor axis, and the distance between $A \in A$ and $B \in B$ the minor axis axis.

axis; then by moving the par round, the pencil in the slider will describe the ellipse.

PROBLEM XXVI.—An ellipse may also be described by means of a string.

Let A B (Fig. 48) be the major axis, and D C the minor axis of




the ellipse, and FG its two foci. Take a string EGF and pass it over the pins, and tie the ends. together, so that when doubled it may be equal to the distance from the focus F to the end of the axis. B; then putting a pencil in the bight or doubling of the string at н and carrying it round, the curve may be traced. This is based on the well known property of the ellipse, that the sum of any two lines drawn from the foci to any

points in the circumference is the same.

PROBLEM XXVII.—The axes of an ellipse being given, to draw the curve by intersections.

Let A C (Fig. 49) be the major axis, and D B half the minor axis. On the major axis construct the parallelogram AEFC, and make its height equal to DB. Divide AE and EB each into the same number of equal parts, and number the divisions from A and E respectively; then join A1, 12, 23, etc., and their intersections will give points through which the curve may be drawn.


The points for a "raking" or rampant ellipse may also be found by the intersection of lines as shown at Fig. 50. Let A c be the major and E B the minor axis: draw AG and CH each parallel to BE, and equal to the semi-axis minor. Divide AD, the semiaxis major, and the lines A G and C H each into the same number of equal parts, in 1, 2, 3 and 4; then from E, through the divisions 1, 2, 3 and 4, on the semi-axis major AD, draw the lines E h, E k, E l, and Em; and from B, through the divisions 1, 2, 3 and 4 on the line A G, draw the lines 1, 2, 3 and 4 B; and the intersection of



these with the lines E 1, 2, 3 and 4 in the points $h \ k \ l \ m$, will be points in the curve.

PROBLEM XXVIII.—To describe with a compass a figure resembling the ellipse.

Let A B (Fig. 51) be the given axis, which divide into three equal parts at the points fg. From these points as centres, with the radius fA, describe circles which intersect each other, and from the points of intersection through f and g, draw the diameters Cg E, CfD. From C as a centre, with the radius CD, describe the arc DF, which



completes the semi-ellipse. The other half of the ellipse may be completed in the same manner, as shown by the dotted lines.

PROBLEM XXIX.—Another method of describing a figure approaching the ellipse with a compass.

The proportions of the ellipse may be varied by altering the ratio of the divisions of the diameter, as thus:—Divide the major axis of the ellipse A B (Fig. 52), into four equal parts, in the points f g h. On f h construct an equilateral triangle f c h, and produce




Fig. 53.

the sides of the triangle C f, C h indefinitely, as to D and E. Then from the centres f and h, with the radius A f, describe the circles A D g, B E g; and from the centre C, with the radius C D, describe the arc D E to complete the semi-ellipse. The other half may be completed in the same manner. By this method of construction the minor axis is to the major axis as 14 to 22.

The following problems, which relate more particularly to handrailing, should be thoroughly mastered before passing to actual work.

A tangent is a line touching a circle at right angles to the radius as shown at Fig. 55.

To construct Fig. 53: From the centre o with the radius o A, describe a quarter-circle A P C; draw tangents A B and C B; join A C; through the point B draw a straight line parallel to A C; with the centre B, with the radius B A, describe the arcs A D and C E; at the point E erect the perpendicular E F at right angles to D E to any desired height; in laying down a hand-rail this height will be the number of risers contained in the wreath; let F be the given height (this being one pitch); join F D; extend O B to G; draw G H at right angles to F D; make G H equal to B I; with the centre H and radius D G describe arcs cutting D F at K and L; draw H L and H K, which are the tangents on the pitch, and which when placed in position would stand plumb over A B C.

To construct Fig. 54, proceed as above until the height is located. It will be seen that here B G is lifted higher, making the pitch line and tangents F G and D G of unequal length. To obtain the angle, continue B G to H, making B H equal to E F; from H draw the line H J to any distance at right angles to D G. With the centre G and radius G F, describe an arc cutting the line H J at I; join I G and I D, and the angle is completed.

An easy way to prove these problems is to draw them on common thick paper; then take a knife, and cut out the angle DEF, place it perpendicularly over ABC, bringing D over A, and E over C; then cut out the angle HLK, and if drawn correctly it will lie on the pitch lines and fit the sides exactly.

To draw the curve line the quickest and most practical method




Fig. 54.

is to take B as a centre, and with a radius of B P, describe an arc, touching the curve A P C, in the angle A B C, from H, as a centre, with the same radius, describe an arc cutting H G at M; then, take a thin flexible strip of wood of an even thickness, bend it until it touches the points K I M; mark around it with a pencil, and the curve is completed, and near enough to absolute accuracy for all practical purposes. \blacksquare





Fig. 55.

PART II.

TO MAKE THE WREATHS FOR STAIRS WITH FOUR WINDERS IN THE WELL.

FIGURE 1.—Strike the quarter circle $A \ B \ C$, which is the centre line of the rail, and also describe the inside and outside lines of rail $b \ b$, and mark the risers at $A \ B$ and C. Draw the lines $A \ D$ and $C \ D$.

FIGURE 2.—Draw the straight line B K equal to the tread of one step, and set up K A equal to the rise of one step. Draw the line A C, and make A D and D C equal to the length A D and D C in Figure 1. Set up the height of two risers from C to F. Draw the line A B, and mark the point G at one third the distance from A to B, and draw the line F G. Continue C A to the point A and from A draw the prependicular line A B. Make the point at A B square to B B and ease off the rail from B to B and draw the top and bottom side, by setting half the thickness of the rail each side the line A B.



Time 1





Fig 2



through them. Take the distance X D, and mark it on the ordinate from c to k, and draw the lines E K and K F. Make the joint L M square to K F, and the end N O square to K E. From I, with the distance I P, describe the arc P Q, and draw Q H, and apply this bevel I Q H, to both ends of the wreath through the centre O, as shown at I Q H in Figure 4. Take the distance Q O in Figure 4, and apply it from I to R in Figure 1; draw R S parallel to I J, and cut it with the line I, S. Apply the distance R S from F to V, and F to W; also from E to T and E to U, and make the face mould the length from T to W.

FIGURE 3.—The centre line E UF, and the joints are the same as E U F in Figure 1. Set the compasses to half the thickness of of the plank CD in Figure 3a, and mark it each side the centre line E UF, and make another face mould to this (Figure 3), mark it on the plank, and cut it out square, and joint the ends square. Now apply the face mould Figure 1 on the top side of wreath, with the points V and T over the points Q Q at the ends of wreath, and mark both edges; apply it on the underside with the points W and U over the points HH, at the ends of wreath, and mark both edges. Work the inside of the wreath with a round plane to fit the rail on the plan, then work off the outside to the marks on the top and bottom, and the bevels at the ends. To work the top: At the mark K P on the face mould, take an equal portion off the top and bottom side of the wreath that will leave it the thickness of the rail, and work it to the bevels marked on the ends, gradually twisting from end to end. The bottom part can be gauged from the top side.

TO MAKE THE WREATHS FOR STAIRS WITH SIX WINDERS IN THE WELL.

FIGURE 4.—Strike the quarter circle A C, which is the centre line of the rail, and also describe the inside and outside lines of rail, $b \ \dot{b} \ \dot{b}$. Draw the lines A D, and D C.

FIGURE 5.—Draw the straight line B K equal to the tread of one step, and set up K A equal to the rise of one step. Draw the line A C, and make A D and D C equal to A D and D C in Figure 4; set up the height of 3 risers from C to F; draw the line A B, and mark the point G at one-third the distance from A to B, and draw the line G F; erect the perpendicular line D J. Joint the rail square at H, (which eases the rail better than if jointed at the spring of the well at A). Ease off the rail from H to E, and draw H I parallel to A C.

FIGURE 4.—Draw the line C G through the centre X, and make C I equal to L H in Figure 2, and draw I H. Set up C F equal to I F in Figure 5, and C I equal to L I; join I I, and from the point F draw the line F G parallel to I I, and join G H.

Draw ordinate lines $a \ b \ b$, at any convenient distance apart, all parallel to $G \ H$, one of which to pass from D to X. From the point I draw the line $I \ N$ square to $I \ J$, and from G, with the distance $G \ H$, cut the line $I \ N$ at E, and draw $G \ E$.

Draw the perpendicular lines a c, and from the points c c c, draw ordinate line c to d d, all parallel to G E. Take the distances from a to b b, and apply them from c to d d, and draw the face mould through them.

Take the distance X D, and mark it on the ordinate from c to K, and draw the line E K and K F. Make the joint L M square to K F, and the end N O square to K E.

From I, with the distance I P, describe the arc P Q, and draw Q H. Apply the bevel I Q H to both ends the wreath through the






Fig. 4





centre O, as shown at I Q H in Figure 4. Take the distance Q on Figure 4, and apply it from I R in Figure 1, and draw R S parallel to G F, and cut it with the line I S. Apply the distance R S from F to V, and F to W, also from E to T and E to U, and make the face mould from T to W.

FIGURE 6.—The centre line $E\ U\ F$ and the joints at the ends, are the same as $E\ U\ F$ in Figure 1. Set the compasses to half the thickness of the plank $C\ D$ in Figure 7, and mark it each side the centre line $E\ U\ F$. Make another face mould, (to Figure 6) mark it on the plank, cut it out square, and joint the ends square.

Apply the face mould, Figure 4, on the top side the wreath, with the points T and V over the points Q Q at the ends of the wreath, and mark both edges. Apply it on the underside the wreath, with the points W and U over the points H H at the ends of the wreath, and mark it.

Work the inside the wreath with a round plane to fit the inside curve on plan, then work off the outside to the marks on the top and bottom and the bevels at the ends.

To work the top, at the mark KP on the face mould, take an equal portion off the top and bottom side the wreath, that will leave it the thickness of the rail, and work it from the bevels at each end, through KP, gradually twisting from end to end. The bottom part can then be gauged from the top side.

TO MAKE THE WREATHS FOR STAIRS WITH THREE WINDERS IN HALF THE WELL, AND LANDING IN THE CENTRE OF THE WELL.

(THIS IS ONE OF THE MOST DIFFICULT RAILS THAT CAN BE MADE.)

FIGURE 8.—Strike out the semi-circle A B C, which is the centre of rail, and also describe the inside and outside lines of rail. Draw the lines C E, A D, and D E.

FIGURE 9 (See Folding Plate).—Draw the straight line O K equal to the tread of one step, and set up KA equal to the rise of one step. Draw the line A E, and make A D—D B and B E equal to A D—D B and B E in Figure 8. Set up the height of 3 risers from E to M, and six inches more from E to E0 E1 to E2 thigh on the landing, or six inches higher than the rail is on the stairs, which should be E2 E2 feet plumb with the face of the risers.)

Draw the line A O, and mark the point G about one-third the distance from A to O, and join C G. Make the joint at H which is a little above the spring of the well at A, and ease off the rail as shown at G.

Draw the line HLI parallel to AB, and erect the perpendicular lines LJ and IE. Now from the base line HLI and the height LJ and IF get the face mould and work the bottom wreath, as shown and described in Figure 5, from the base line HLI and the heights LJ and IE.

To work the top wreath proceed as follows, viz.:-

FIGURE 10.—Lay down the plan of the rail, the centre line $B \subset F$, being the same as $B \subset F$, in Figure 8, and make the straight part about 5 inches from C to F. Draw the lines FA-A B-B E and EF. Take the height $N \subset F$ in Figure 9, and apply it from F to D, and join $A \subset D$. Draw $D \subset F$ square to $A \subset D$, and make $D \subset G$ equal to $F \subset F$.





Fig. 8.



Draw ordinate lines a b b b parallel to A B, and draw the lines a c, and from c \bar{c} , draw ordinate c d d d, parallel to G D. Apply the distance from a to b, b, b, on to the ordinates from c to d, d, d, and draw the face mould through them. Make the joints at H and D square, as shown.

FIGURE 11.—Shows the ends of the wreath. Take the bevel F D A in Figure 10 and apply it at the top end of the wreath through the centre O at F D A, and mark the size of the rail on as shown.

FIGURE 12.—Is the face mould to cut the wreath out square; the centre line DIH, and the joints are the same as the centre line DIH in Figure 3; put half the thickness of the plank each side the centre line DIH, and cut out the wreath, Figure 8: Take half the thickness of the plank from A to L, draw LM parallel to AD, and draw AM, apply the distance LM to HI, and HK, and make the face mould from I to I.

Apply Figure 10 face mould on the top side of wreath, with the points D and J, over the points D J in Figure 11, and mark it. Apply it on the underside with the points D and K over the points A and K in Figure 11.

Work it as described in the preceding Figures 6 and 7, to the bevels at the ends as shown, and work the part from D to I straight; then work the top gradually twisting from I to I in Figure 12.

TO MAKE THE WREATHS FOR STAIRS WITH ONE RISER IN THE CENTRE OF WELL.


Take the length of the ordinate O H, and apply it on the ordinate from P to Q, and draw the lines N Q, and L Q. Make the joint R S square to Q L, and the joint M N square to Q N.

FIGURE 14.—The centre line N 7 7 7 L, and the joints at ends, are the same as Figure 13.

Set the compasses to half the thickness of the plank, (as shown at C D in Figure 15), and apply it on each side the centre line L 7 7 7 N, and draw the inside and outside lines. Mark this face mould on the plank, and cut it out square, and joint the ends square.

To put the twist on the wreath, proceed as follows:-

In Figure 13 from the centre J, describe the arc T U, and draw U E. Continue the lines I E, and G H, until they meet at W. Take the length G L and apply it from G to V, and draw V W. From G draw G X square to V W, and describe the arc X Y, and draw Y U.



lg. 14.

g. 15.

Take the bevel U J E, and apply it on the bottom end of the wreath in Figure 15, at U J E, through the centre O, and mark half the width of the rail on each side U E, also mark the top and bottom line of rail square to UE. Apply the bevel HYI in Figure 1 to HYI, at the top end of the wreath in Figure 15, through the centre O, and mark the size of the rail on as shown. Mark the line Q P on both sides the wreath. Take the distance Q U in Figure 15, and apply it from J to a in Figure 13, draw a b parallel to JK, and draw Jb, apply the distance ab from N to c and N to d. Apply the distance O Y, in Figure 15, to X e in Figure 13, and draw e f parallel to GV, and apply the distance Xf to Lg, and L h. Make a face mould to Figure 13, the full length from c to h, and place it on the top of the wreath, with the point g over the point Y, in Figure 15, at the top end of the wreath, and the point c over the point U, at the bottom end and mark both edges, then mark it on the underside the wreath, with the point h over the point I in Figure 15, and the point c over the point E.

First work off the inside of the wreath with a round plane that will fit the rail on the plan, then work off the outside part. To work the top at the mark Q P, take an equal portion off the top and bottom side of the wreath that will leave it the finished thickness of the rail, then work from the bevels marked at each end, through the part taken off at Q P and the bottom part can be gauged from the top.

TO MAKE THE WREATHS FOR LEVEL LANDING STAIRS. THE DISTANCE BETWEEN CENTRE OF RAILS ACROSS THE WELL BEING EQUAL TO THE TREAD OF A STEP, OR NEARLY SO.


FIGURE 16.—A B C is the centre of the rail, A B being equal to the tread of one step. Strike out the inside and outside of the rail b b b b. Draw C D and D A. Set up E F equal to one riser, and draw D F to G, and draw the line C G. Draw ordinate lines a b b, at any convenient distance apart, and draw the lines a, c. From the points c c draw ordinate lines c d, square to the line D G. Take the distance a b b, and apply them on the ordinates from c to d d, and draw the face mould through them.

Take the thickness of the plank C A in Figure 18, and apply it from D to I in Figure 16, draw I H parallel to D F, and cut it with the line of D H. Take half of I H and apply it from K to L, and K to J. Make the face mould the length from J to G, and mark it on the top side of the plank, and cut the two joints at J and G square.

Take the bevel DJE in Figure 16, and apply it to the top joint at DFE, as shown in Figure 18. The bottom end will be square, as shown in Figure 17.

Apply the face mould underside the wreath with the point L at the lower end of wreath. Cut it out bevel (as this kind of wreath is less labor cut bevel than having to bevel it if cut out square).

Take an equal portion off the top and bottom side of the shank part of wreath to leave the rail the finished thickness as shown in Figure 17, at the bottom end, then gradually work the top side twisted to the bevel at the top end, so that when the wreath is put up to its proper pitch the top side is level across. Gauge the bottom from the top side.







Fig. 17.



Note.—The distance across the well between centre of rails should not exceed the tread of a step for level landing stairs, or the wreath has the appearance of dropping.

If the distance is less than the tread of a step bevel ordinate lines would be required, after the manner shown in Figures 13, 14, and 15.

TO MAKE THE WREATH FOR QUARTER-LANDING STAIRS, HAVING ONE WINDER IN THE WELL.

FIGURE 19.—From the centre O strike the quarter circle A B, the centre of the rail, and draw the lines O A—O B—B C and A C, and draw the inside and outside curve of rail.

Figure 20 (See Folding Plate).—Make D E equal to the tread of one step, and E A equal to one riser.

Draw the line A B and make A B and B C equal to A B and B

C in Figure 19.

Set up the height of 2 risers from B to F, and draw the line F G, to pitch of the stairs. Join A D and mark the point H about one-third the distance from A to D, then mark the point I about one-third the distance from F to G, and draw the line I H.

Draw the perpendicular line CJ, and continue AB to K. Joint the end at K square to JK and ease off the rail at H. Joint the top length at the point L and ease off the rail at I.

Apply the distances $a \ b \ b$, on to the ordinates from c to $d \ d \ d$,

and draw the face mould through the points d d d.

Mark the length of the ordinate O C, on to the ordinate from c to H, and draw H G and H M. Joint the end at G square to G H.

Take the distance ML in Figure 20, and apply it from M to T, and joint the end at T square to H T. Apply the bevel K I E to both ends the wreath as shown in Figure 22.





Fig. 19.

The face mould Figure 21, is got from the centre line of Figure 19, as before described, and the joints at T and G are the same as in Figure 19.

Apply the distance O I, in Figure 22 to K L in Figure 19, draw L N, and mark the length L N from G to P and G to Q, also from T to S and T to R. Make the face mould Figure 19, the length from P to R.



Cut the wreath out square to Figure 21, face mould and joint the ends. Apply Figure 19 face mould on the top side of wreath with the points SP, over II at the ends of wreath, then apply it underside with the points RQ, over EE at the ends.

Work the inside the wreath first with a round plan to fit the rail on plan, and work the top side straight from T to M and d to G in Figure 21, and gradually work it twisted to the bevels at each end, and take an equal portion off the top and bottom side at c H to leave the rail the finished thickness.

TO MAKE THE WREATH FOR QUARTER LAND-ING STAIRS, WITH THE RISERS AS SHOWN IN FIGURE 23.

FIGURE 23.—From the centre O strike the quarter circle A B, which is the centre of the rail, draw the lines O A—O B—B C and A C, and draw the straight part each end about 3 inches long from A to D, and B to E, then draw the inside and outside lines of rail.

FIGURE 24 (See Folding Plate) —Make D E equal to one tread, and E A equal to one riser. Draw the line A B, the parts A C and C B, being equal to A C and C B in Figure 1. Set up B F equal to one riser and from F draw the line G F H, to the pitch of the stairs, and draw C G.

Join A D, and mark the point I about half way between A and D, and draw I G.

Make K J equal to A D in Figure 23, and joint the end at J, square to I G, draw the line J N.

Make FL equal to EB in Figure 23, draw LM and joint the end at M square to FH.


FIGURE 23.—Draw the line D J, set up B F equal to O G in Figure 24, and joint J F.

Set up B G equal to N F in Figure 24, and from the point G draw G H parallel to J F.

From J, draw J I square to J F, and from H with the distance H D, cut J I at K, and draw H K.

Draw the ordinates a b b b, parallel to H D, draw the lines a c, and from the point c, draw ordinate c d d parallel to H K; apply the distance a b b b, on to the ordinates c d d d, and draw the face mould through the points d d d.

Mark the length of the ordinate a C, on the ordinate c L, and draw L K and L G.



Make G M equal to F M in Figure 24. Joint the end at K square to K L, and the end at M square to L M.

Get the level $O\ J\ D$ for the bottom end, and $B\ S\ O$ for the top end of wreath, as described in Figure 15, and apply them at the ends as shown in Figure 26.

The face mould Figure 25, is obtained from the centre line of Figure 23, as described in previous examples.




Fig. 26.

Apply the distance T U from K to V, and K to W, and the length R Y apply from M to g, and M to f, and make Figure 23, face mould the length from V to f.

Cut the wreath out square, to Figure 25, face mould, and joint the ends.

Apply Figure 23, face mould on the top of wreath, with the points f and W over the points S and O at the ends of wreath, then mark it underside with the points g and V, over the point H and D at the ends of wreath. Proceed to work the wreath as before described, to the bevels at the ends, and take as much of the top and bottom sides of the wreath at L a as will leave the rail the finished thickness.

5675 H75

THE LIBRARY UNIVERSITY OF CALIFORNIA Santa Barbara

THIS BOOK IS DUE ON THE LAST DATE STAMPED BELOW.



3 1205 00334 4205

VK



A 000 588 285 7

